

Packing

The packaging materials of the CT Scanner Unit including 7 Cases, are all nontoxic and harmless and users can dispose of them according to own actual condition.

Total Net Weight: 2420 Kg

Total Gross Weight: 4200 kg

1. Case Number 1: CT Gantry


Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
2985	1146	2483	8,49	1220	2100





2. Case Number 2: Patient Table

Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
2969	960	1650	4,69	565	850



3. Case Number 3: Accessories Case

Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
1380	1380	970	1,85	177	305

4. Case Number 4: Main outside Cover

Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
2500	2200	1090	5,99	135	395

5. Case Number 5: Other Covers

Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
2280	1280	1070	3,12	120	260

6. Case Number 6: PDU

Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
623	623	939	0,36	113	130

7. Case Number 7: Tools Case




Box Material:

Wood

Box dimension:

Length in mm	Width in mm	Height in mm	Volume in m3	Net Weight in kg	Gross Weight in Kg
1370	780	820	0,89	90	160






Labeling of the boxes:





Transportation and storage conditions:

Range of ambient temperature: -20°C ~ +55°C;
Range of relative humidity: <80%
Range of atmospheric pressure: 500 ~ 1060hPa.

Explanation of symbols:

	<p>The RECY symbol on the packaging has a similar meaning to the "green dot", but is especially valid for paper and cardboard. RECY guarantees the disposal and material recycling of all transport and outer packaging marked with the RECY symbol.</p>
	<p>Top - The package must always be transported, handled and stored in such a way that the arrows point upwards at all times. Rollers, flaps, strong tilting or edges as well as other forms of handling must be omitted. However, the cargo does not have to be stowed "on top".</p>
	<p>Fragile packaged goods - Goods marked in this way must be handled with care and must in no way be overturned or tied.</p>
	<p>Protect from moisture - Goods marked in this way must be protected from excessive humidity, so they must be stored in a covered place. If particularly heavy or bulky packages cannot be stored in halls or sheds, they must be carefully covered with tarpaulin.</p>
	<p>Indicates the temperature limits to which the medial device can be safely exposed</p>

	<p>Indicates the range of humidity to which the medical device can be safely exposed.</p>
	<p>Indicates the range of atmospheric pressure to which the medical device can be safely exposed</p>